

# Decal Installation Instructions

## ***SURFACE PREPARATION***

All surfaces should be considered dirty and should be cleaned prior to application of vinyl lettering or graphics. Clean the area where the vinyl will be applied. Rubbing alcohol is preferable. Then, rinse area thoroughly and dry.

## ***TEMPERATURE REQUIREMENTS***


Air and application surface should be above 40 degrees F. Best conditions are between 60 – 80 degrees F.

## ***TOOLS NEEDED***

- 1 qt. Spray bottle
- Scissors and/or Razor blade
- Squeegee (credit card will do)
- Blow dryer
- Tape measure
- Friend to help.

## ***APPLICATION***

1. Fill Spray Bottle with water until full, with 2 drops of dishwashing liquid.
2. Cut off excess vinyl around edge of Decal and discard.



3. Hold stripe or graphic next to vehicle or surface to give you an idea of where it's going to go.



4. Spray entire area of vehicle or surface that is going to receive graphic with water solution.



5. Peel backing off of graphic.




6. Lightly wet the tacky part of the sticker with the water solution. Both the receiving surface and the sticker should be wet.
7. Place the sticker on the surface where you want it and slide it into position.



8. Now squeegee out the water and bubbles.



9. Let the graphic sit for a few minutes, then spray the top of the sticker's backing tape to neutralize the tape's glue. Then squeeze again.
10. SLOWLY peel the tape off at an angle. If decal begins to pickup Stop, replace the tape, squeegee and let it dry some more.



11. Once off, wet sticker once more and squeegee out any leftover bubbles.



12. Use blow dryer to carefully dry.
13. Dry decal carefully and let sit for 24 hours before washing and waxing, or driving in inclement weather (rain/snow/freezing temp). Your vehicle is still drivable; the decals will not fly off.
14. Next day, check all of the edges for lifting by rubbing over them with your finger.